

Construction update of Botanica-1st
JULY,2024
PHASE-I

1.Cluster-03,Unitno.11to15

- Civil sub structure works complete.
- Ground floor slab completed.
- 1st floor slab completed
- Roof slab completed
- Brickwork work completed
- Plastering work completed
- Internal Electrical Wiring work completed.
- Internal Plumbing work in progress
- Water Proofing is completed
- Pop work in progress.
- Anti termite work completed
- Flooring work is in progress.
- External paint is in progress.
- Finishing work is on progress.

2.Cluster-4, Unitno.16 to 21

- Civil substructure works foundation completed.
- Ground floor slab completed.
- 1st floor slab completed.
- Brickwork work in progress
- Roof slab is completed.
- Electrical work is in progress.
- Internal Plumbing work in progress
- Plastering work is in progress.
- Anti termite work completed.
- Waterproofing completed.
- Flooring work in progress.
- External paint is in progress.
- Finishing work is on progress.

3.Cluster-15,Unitno.57to 59

- Civilsubstructureworksfoundation complete.
- Ground Floor slab completed.

- 1st floor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Electrical wiring work in completed.
- Internal Plumbing work in progress
- Waterproofing work completed.
- Pop work in progress.
- Flooring work in progress.
- Anti termite work completed.
- External paint is in progress.
- Finishing work is in progress.

4.Cluster-16,Unitno.34to37

- Civilsub-structureworkscompleted.
- Civil super-structure works completed.
- Ground floor slab completed.
- 1stfloor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Plumbing work in progress.
- Internal Electrical Work is in progress.
- Water Proofing completed.
- Pop work in progress.
- Anti termite work completed.
- Flooring work in progress.
- External paint is in progress.
- Finishing work is on progress.

5.Cluster-17,Unitno.26 to 33

- Civil substructure works foundation completed.
- Ground floor slab completed.
- Brickwork work in progress.
- 1st floor slab completed.
- Internal Electrical work in progress.
- Roof slab is completed.
- Plastering work is in progress.
- Internal Plumbing work in progress.
- Anti termite work completed.
- Waterproofing work is in progress.
- Flooring work is in progress.(Except-27)
- External paint is in progress.

- Finishing work is on progress.(except-27)

6.Cluster–19,Unitno.38to47

- Civilsub-structureworks foundation complete.
- Ground floor slab completed.
- Brickwork work in progress.
- First floor slab completed.
- Internal Electrical Wiring work in progress..
- Roof slab completed.
- Plastering work in progress.
- Internal Plumbing work in progress.
- Anti termite work completed.
- Waterproofing work is completed.
- Flooring work is in progress.(Except-38)
- External paint is in progress.
- Finishing work is on progress.

7.Cluster–20,Unitno.48to56

- Civilsubstructureworksfoundation complete.
- Ground floor slab completed.
- Brickwork work in progress.
- First floor slab completed.
- Internal Electrical Wiring work in progress.
- Roof slab completed.
- Plastering work in progress.
- Internal Plumbing work in progress.
- Pop work in progress.
- Anti termite work completed.
- Waterproofing is in progress.
- Flooring work is in progress.
- External paint is in progress.
- Finishing work is on progress.

8.Cluster–21,Unitno.63 to 70

- Civil substructure works foundation complete.
- Ground Floor slab completed.
- Brickwork work in progress
- 1st floor slab completed.
- Roof slab is completed.
- Internal Electrical work in progress.
- Plastering work is in progress.
- Internal Plumbing work in progress.
- Anti termite work completed.
- Waterproofing is in progress.
- Flooring work is in progress.(63 to 70)

- External paint is in progress.
- Finishing work is on progress.

9.Cluster-22,Unitno.71to78

- Civilsubstructureworksfoundation complete.
- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork work is completed.
- Internal Electrical work is completed.
- Plastering work in completed.
- Internal Plumbing work in progress.
- Pop work in progress.
- Anti termite work completed.
- Waterproofing work is in progress.
- Flooring work is in progress.(71 to 78)
- Finishing work in progress.(72,73,74,75,78)

10.Cluster-23,Unit no. 87 to 92

- Civil substructure works foundation completed.
- Ground Floor Slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork work in progress.(87 to 92)
- Internal Electrical work in progress.
- Plumbing work is in progress.
- Plastering work is in progress.
- Anti termite work completed.
- Waterproofing work is in progress.
- Flooring work is in progress.(87 to 92)
- External paint is in progress.
- Finishing work is on progress.

11.Cluster-29, Unit no.98 to 99

- Sub structure is completed.
- Ground floor slab is completed.
- Brick work is in progress.
- 1st floor slab completed.
- Roof slab is completed.
- Internal Electrical work in progress.
- Plaster work is in progress.
- Plumbing work is in progress.
- External paint is in progress.
- Flooring work is in progress.

12.Cluster-30, Unit no.93 to 97

- Substructure work completed.
- Ground Floor Slab completed.
- 1st floor slab completed.
- Roof slab is completed.
- Brick work is in progress.
- Internal Electrical work in progress.
- Plaster work is in progress.
- Plumbing work is in progress.
- Anti termite work completed.
- Waterproofing completed.
- Flooring work is in progress.(93 to 97)
- Finishing work is in progress.

13.Cluster-31, Unit no. 83 to 86

- Civil substructure works foundation completed.
- Ground floor slab completed.
- 1st floor slab complete.
- Brick work is in progress.
- Roof slab is completed.
- Plaster work is in progress.
- Anti termite work completed.
- Waterproofing work in progress.
- External paint is in progress.
- Flooring work is in progress.(83 to 86)
- Finishing work is in progress.

14.Cluster-32, Unit no.79 to 82

- Civil substructure works foundation completed.
- Ground Floor Slab completed.
- First floor slab completed.
- Brickwork work in progress.
- Internal Electrical work in progress.

- Roof slab completed.

- Plastering work in progress.

- Internal Plumbing work in progress
- Anti termite work completed
- Flooring work is in progress.
- Waterproofing is completed.
- External paint is in progress.
- Finishing work is in progress.

15.Cluster-33,Unit no. 60 to 62

- Civil substructure works foundation completed.
- Ground floor slab completed.

- 1st floor slab completed.
- Brickwork work in progress.
- Roof slab is completed.
- Internal Electrical work in progress
- Plastering work in progress.
- Plumbing work is in progress.
- Anti termite work completed.
- Waterproofing is in progress.
- Flooring work is in progress.
- External paint is in progress.
- Finishing work is on progress.

CLUB:

- Piling Completed.
- Excavation work in progress.
- Basement Raft Completed.
- Retaining Wall completed.

ROAD

- Flooring work of road is in progress at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- Landscape work is started.