

Construction Update of Botanica-30th SEPTEMBER,2024

PHASE-I

1.Cluster–03,Unitno.11 to 15

- ▣ Civil sub structure works complete.
- ▣ Ground floor slab completed.
- ▣ 1st floor slab completed
- ▣ Roof slab completed
- ▣ Brickwork work completed
- ▣ Plastering work completed
- ▣ Internal Electrical Wiring work completed.
- ▣ Internal Plumbing work in progress
- ▣ Water Proofing is completed
- ▣ Pop work in progress.
- ▣ Anti termite work completed
- ▣ Flooring work is in progress.
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

2.Cluster–4, Unitno.16 to 21

- ▣ Civil substructure works foundation completed.
- ▣ Ground floor slab completed.
- ▣ 1st floor slab completed.
- ▣ Brickwork work in progress.
- ▣ Roof slab is completed.
- ▣ Electrical work is in progress.
- ▣ Internal Plumbing work in progress

- ▣ Plastering work is in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing completed.
- ▣ Flooring work in progress.
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

3.Cluster–15,Unitno.57to 59

- ▣ Civilsubstructureworksfoundation complete.
- ▣ Ground Floor slab completed.
- ▣ 1st floor slab completed.
- ▣ Roof slab completed.
- ▣ Brickwork completed.
- ▣ Plastering work completed.
- ▣ Internal Electrical wiring work in completed.
- ▣ Internal Plumbing work in progress
- ▣ Waterproofing work completed.
- ▣ Pop work in progress.
- ▣ Flooring work in progress.
- ▣ Anti termite work completed.
- ▣ Finishing work is in progress.
- ▣ External paint is in progress.

4.Cluster–16,Unitno.34 to 37

- Civil sub-structure works completed.

- Civil super-structure works completed.
- Ground floor slab completed.
- 1st floor slab completed.
- Roof slab completed.
- Brickwork completed.
- Plastering work completed.
- Internal Plumbing work in progress.
- Internal Electrical Work is in progress.
- Water Proofing completed.
- Pop work in progress.
- Anti termite work completed.
- Flooring work in progress.
- Finishing work is on progress.
- External paint is in progress.

5.Cluster–17,Unitno.26 to 33

- ▣ Civil substructure works foundation completed.
- ▣ Ground floor slab completed.
- ▣ Brickwork work in progress.
- ▣ 1st floor slab completed.
- ▣ Internal Electrical work in progress.
- ▣ Roof slab is completed.
- ▣ Plastering work is in progress.
- ▣ Internal Plumbing work in progress.

- ▣ Anti termite work completed.
- ▣ Waterproofing work is in progress.
- ▣ Flooring work is in progress.
- ▣ Finishing work is on progress.(except-27)
- ▣ External paint is in progress.

6.Cluster–19,Unitno.38to47

- ▣ Civilsub-structureworks foundation complete.
- ▣ Ground floor slab completed.
- ▣ Brickwork work in progress.
- ▣ First floor slab completed.
- ▣ Internal Electrical Wiring work in progress..
- ▣ Roof slab completed.
- ▣ Plastering work in progress.
- ▣ Internal Plumbing work in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing work is completed.
- ▣ Flooring work is in progress.
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

7.Cluster–20,Unitno.48 to56

- ▣ Civilsubstructureworksfoundation complete.
- ▣ Ground floor slab completed.
- ▣ Brickwork work in progress.
- ▣ First floor slab completed.

- ▣ Internal Electrical Wiring work in progress.
- ▣ Roof slab completed.
- ▣ Plastering work in progress.
- ▣ Internal Plumbing work in progress.
- ▣ Pop work in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing is in progress.
- ▣ Flooring work is in progress.
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

8.Cluster–21,Unitno.63 to 70

- ▣ Civil substructure works foundation complete.
- ▣ Ground Floor slab completed.
- ▣ Brickwork work in progress
- ▣ 1st floor slab completed.
- ▣ Roof slab is completed.
- ▣ Internal Electrical work in progress.
- ▣ Plastering work is in progress.
- ▣ Internal Plumbing work in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing is in progress.
- ▣ Flooring work is in progress.(63 to 70)
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

9.Cluster–22,Unitno.71to78

- ▣ Civil substructure works foundation complete.
- ▣ Ground floor slab completed.
- ▣ 1st floor slab completed.
- ▣ Roof slab completed.
- ▣ Brickwork work is completed.
- ▣ Internal Electrical work is completed.
- ▣ Plastering work in completed.
- ▣ Internal Plumbing work in progress.
- ▣ Pop work in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing work is in progress.
- ▣ Flooring work is in progress.(71 to 78)
- ▣ Finishing work in progress.(71,72,73,74,76,75,77,78)
- ▣ External paint is in progress.

10.Cluster–23,Unit no. 87 to 92

- ▣ Civil substructure works foundation completed.
- ▣ Ground Floor Slab completed.
- ▣ 1st floor slab completed.
- ▣ Roof slab completed.
- ▣ Brickwork work in progress.(87 to 92)
- ▣ Internal Electrical work in progress.
- ▣ Plumbing work is in progress.
- ▣ Plastering work is in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing work is in progress.
- ▣ Flooring work is in progress.(87 to 92)

- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

11.Cluster–29, Unit no.98 to 99

- ▣ Sub structure is completed.
- ▣ Ground floor slab is completed.
- ▣ Brick work is in progress.
- ▣ 1st floor slab completed.
- ▣ Roof slab is completed.
- ▣ Internal Electrical work in progress.
- ▣ Plaster work is in progress.
- ▣ Plumbing work is in progress.
- ▣ Flooring work is in progress.
- ▣ Finishing Work is in progress.
- ▣ External paint is in progress.

12.Cluster–30, Unit no.93 to 97

- ▣ Substructure work completed.
- ▣ Ground Floor Slab completed.
- ▣ 1st floor slab completed.
- ▣ Roof slab is completed.
- ▣ Brick work is in progress.
- ▣ Internal Electrical work in progress.
- ▣ Plaster work is in progress.
- ▣ Plumbing work is in progress.

- ▣ Anti termite work completed.
- ▣ Waterproofing completed.
- ▣ Flooring work is in progress.(93 to 97)
- ▣ Finishing work is in progress.
- ▣ External paint is in progress.

13.Cluster-31, Unit no. 83 to 86

- ▣ Civil substructure works foundation completed.
- ▣ Ground floor slab completed.
- ▣ 1st floor slab complete.
- ▣ Brick work is in progress.
- ▣ Roof slab is completed.
- ▣ Plaster work is in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing work in progress.
- ▣ External paint is in progress.
- ▣ Flooring work is in progress.(83 to 86)
- ▣ Finishing work is in progress.
- ▣ External paint is in progress.

14.Cluster-32, Unit no.79 to 82

- ▣ Civil substructure works foundation completed.
- ▣ Ground Floor Slab completed.
- ▣ First floor slab completed.
- ▣ Brickwork work in progress.
- ▣ Internal Electrical work in progress.
- ▣ Roof slab completed.
- ▣ Plastering work in progress.

- ▣ Internal Plumbing work in progress
- ▣ Anti termite work completed
- ▣ Flooring work is in progress.
- ▣ Waterproofing is completed.
- ▣ Finishing work is in progress.
- ▣ External paint is in progress.

15.Cluster–33,Unit no. 60 to 62

- ▣ Civil substructure works foundation completed.
- ▣ Ground floor slab completed.
- ▣ 1st floor slab completed.
- ▣ Brickwork work in progress.
- ▣ Roof slab is completed.
- ▣ Internal Electrical work in progress
- ▣ Plastering work in progress.
- ▣ Plumbing work is in progress.
- ▣ Anti termite work completed.
- ▣ Waterproofing is in progress.
- ▣ Flooring work is in progress.
- ▣ Finishing work is on progress.
- ▣ External paint is in progress.

CLUB:

- ▣ Piling Completed.
- ▣ Excavation work in progress.
- ▣ Basement Raft Completed.
- ▣ Retaining Wall completed.
- ▣ Ground floor slab complete .

ROAD

- ▣ Flooring work of road is completed at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- ▣ Landscape work is started.