

A photograph of a narrow, dimly lit hallway. The walls are in poor condition, with significant peeling and missing paint, particularly on the left side. The floor is a light-colored, possibly concrete or tiled surface, showing some wear and discoloration. At the end of the hallway, there is a dark doorway leading to another area. The lighting is low, creating deep shadows and highlighting the textures of the peeling paint and the floor.

Block - 1/10 Floor  
Lobby Area