## THE KOLKATA MUNICIPAL CORPORATION

## WATER SUPPLY DEPARTMENT

SAVE WATER SAVE LIFE

## SANCTION ORDER

SAVE WATER SAVE LIFE

(Sanction/Permission for private water supply connection/or

Other works under provisions of sections

i) 258 read with sec. 558

ii) 254 read with sec. 260

iii) 235,236,239 read with sec. 260 of CMC Act, 1980)

Building Case No.:

2023110273

Date: 28/09/2023

Building Plan Sanction No.: 2023110326

Date: 05/01/2024

Borough No.: 11 Ward No.: 114

Assessee No.:

311141202885

GURU CHARAN NASKAR ROAD

Premises No. & Street Name: 185 Owner Name: SRI TARAK NATH MONDAL, SMT KALP

Name of KMC Licensed Plumber: SRI KAMAL KRISHNA MONDAL

Address of Plumber: 2135, PURBAPUTIARY DAKHIN PARA .. 700093

Purpose: CONSTRUCTION

NEW

Budget Code	Description		Amount
4231/211	Deposit money for water connection - 4231/211	0	
4231/212	Road opening fees - 4231/212		. 35€
4231/231	Extra road restoration - 4231/231		9783
4210/221	Annual fees for domestic purpose water supply - 4210/221		()
4210/262	Sale of water for non domestic purpose (ICI) - 4210/262		()
4210/299	Miscellaneous - 4210/299	A	374
4231/211	Fees for water connection - 4231/211		19900

Total Amount: 20513

Receipt No.: E/07/2023/5592

Date: 04/01/2024

Mode of Payment: Online

Details of Water Fittings:

Stop Cock Size:	25	Service Pipe Size:	25,20	Water Tap Size:	15	Ferrule Size:	20	
				1 .1	_	,		

Read Opening Date: From 24/01/24 to 25/01/24

1) The above demand amount excludes physical execution of the work through KMC licensed plumber involving material, manpower & tools & plant cost.

2) Owners of the premises shall have to maintain all water fittings to prevent stagnation due to leakage & drain off water once a week from underground & overhead reservoirs and covered properly with well fitted lids for safeguard against contamination and mosquito breeding. Non-compliance may lead to cut off water connection u/s 275(b) of CMC Act, 1980 and will be treated as offence u/s 496 of the CMC Act. Ball cock is to be installed at underground reservoir to save water. It is also encouraged to install automatic pump tripping arrangement to avoid overflow from overhead reservoir.


\*\* As this is a computer generated document, it does not require actual signature

Assistant Engineer(W.S)

Executive Engineer (W.S./9

Ex. Engineer Water Supply Deptt Br. XÌ (J. U)

Assistant Engineer Water Supply Deptt. Br. XI (J. U)



Scanned with CamScanner