

PARTY'S COP

a) Don't dispose of debris indiscriminately.
b) Don't allow the vehicles to run at high speed within the work of Don't cut materials without proper dust control/holse control Don't keep materials without effective cover.
d) Don't keep materials without effective cover.
e) Don't ellow access in the work area except workers to lime of Don't have the soil, sand and gement stack uncovered.
f) Don't keep materials or debris on the roads or pavements.
g) Don't keep materials or debris on the roads or pavements.
h) Burning of old tyres in hot mix plant as a fuel during construction of the coal tar should be discarded: