

05/10/2020

Gmail - RE: DEFFECTIVE DELIVERY OF FLAT/TOWER ISSUESOF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ ...

 Gmail

Annapurna. PAHC <annapurnatower@gmail.com>

RE: DEFFECTIVE DELIVERY OF FLAT/TOWER ISSUESOF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ PRAKRITI

Annapurna. PAHC <annapurnatower@gmail.com> Wed, Dec 4, 2019 at 2:06 PM
To: Customer Care <CustomerCare.gpl@godrejproperties.com>
Cc: "cco@godrejproperties.com" <cco@godrejproperties.com>, "akshay.dewan@godrejproperties.com" <akshay.dewan@godrejproperties.com>, "customercare.gpl@godrejproperties.com" <customercare.gpl@godrejproperties.com>, "subha.chakrabarti@godrejproperties.com" <subha.chakrabarti@godrejproperties.com>, "manmeet.dhanjal@godrejproperties.com" <manmeet.dhanjal@godrejproperties.com>
Bcc: "ANNA 808 MR.ARUP RATAN DAS" <arupdas5@rediffmail.com>, ANNA 1603 HINDOL GHOSH <hkoman2008@gmail.com>, nkayfbd3387@gmail.com

Dear Mr. Muzammil Dingankar
Customer centricity

Further to our mail date in continuation to your advise dated 3rd December, 19, we are attaching the latest photos to establish our demand to show how haphazardly parking has been allotted by your Kolkata office. This is unscientific and will be very difficult to reach out at the designated parking lot.

With regards,

Nandan Kumar Ray
N 510 #7701949449

[Quoted text hidden]

3 attachments



NO PILLAR MARKINGS.jpg
4503K




HAPAZARD ALLOTMENT 1st photo.jpg
4630K

HAPAZARD ALLOTMENT 2nd photo.jpg

10/2020

Gmail - RE: DEFFECTIVE DELIVERY OF FLAT/TOWER ISSUES OF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ ...

4587K





Annapurna. PAHC <annapurnatower@gmail.com>

RE: DEFFECTIVE DELIVERY OF FLAT/TOWER ISSUES OF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ PRAKRITI

Annapurna. PAHC <annapurnatower@gmail.com> Wed, Dec 4, 2019 at 2:26 PM
 To: Customer Care <CustomerCare.gpl@godrejproperties.com>
 Cc: "cco@godrejproperties.com" <cco@godrejproperties.com>, "akshay.dewan@godrejproperties.com" <akshay.dewan@godrejproperties.com>, "customercare.gpl@godrejproperties.com" <customercare.gpl@godrejproperties.com>, "subha.chakrabarti@godrejproperties.com" <subha.chakrabarti@godrejproperties.com>, "manmeet.dhanjal@godrejproperties.com" <manmeet.dhanjal@godrejproperties.com>
 Bcc: "ANNA 808 MR.ARUP RATAN DAS" <arupdas5@rediffmail.com>, ANNA 1603 HINDOL GHOSH <hkoman2008@gmail.com>, nkrayfd3387@gmail.com

Dear Mr. Muzammil Dingankar

Customer centricity

Further to our mail date in continuation to your advise dated 3rd December, 19, we are attaching the latest photos on shabby finish and incomplete service parapet wall which is not suitable for use in case service is to be rendered. More over cracks have come out in the outer ground floor of the building along with seepage at the main entrance Pillar/foundation beam in the left side.

Lastly, we would again request you to confirm that the Annapurna tower is under West Bengal HIRA Act and accordingly, the defect liability of construction should be incorporated as 5 years and any defect found by a allottee should be rectified within 30 days, as per laid down Act, The above clause is being violated in a systematic way by your concerned department in rectifying the genuine defects pointed out by us.

Nandan Kumar Ray
 N 510 #7701949449

[Quoted text hidden]

7 attachments



SEEPAGE AT MAIN ENTRANCE RT.SIDE.jpg
 103K

CRACKS ON WALL 2.jpg
 33K

05/10/2020

Gmail - RE: DEFECTIVE DELIVERY OF FLAT/TOWER ISSUES OF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ ...



CRACKS ON WALLS.jpg
32K



SERVICE PARAPET 2.jpg
2703K



NASTY FINISH.jpg
3183K



SERVICE PARAPET 1.jpg
3159K

SERVICE PARAPET 3.jpg
3509K

05/10/2020

Gmail - RE: DEFFECTIVE DELIVERY OF FLAT/TOWER ISSUESOF ANNAPURNATOWER, N-BLOCK, MATHBAGAN GODEREJ ...

