



Clotting of tower in 10th floor of EVEREST

1 message

Ajay Kumar <ajaybkp2015@gmail.com>

Wed, 15 Apr 2020 at 21:06

To: PM Godrejprakriti <PM.Godrejprakriti@in.knightfrank.com>, Palash Das <palashd@godrejproperties.com>, Abhikendra <abhikendra.saha@godrejproperties.com>

Cc: everest.pahc@gmail.com, Raktim Mukherjee <raktim.mukherjee@godrejproperties.com>

Dear Mr Raktim and Palash Das,

I would. Like to inform that since after shifting to my flat this is the first day if heavy rain.

I found clotting of water in my balconies and in front of my main gate...

Due to non absense of Shades at balconies and Common passage of each floor it's very risky for us to survive and also it will destroy our interior works.

I need immediate action by godrej on the same just after the Lockdown and construction of shades in my flat.

Before purchase of Flat in Godrej the other towers shown to me is already constructed with shades in balconies.

Hence please do the needful without delay.

. Hope for your kind cooperation.

Regards,
Ajay bawra
Everest 1012