



Fire Sprinklar Blocked

1 message

Ajay Kumar <ajaybkp2015@gmail.com>

Sat, 3 Aug 2019 at 15:52

To: Helpdesk Godrejprakriti <Helpdesk.Godrejprakriti@in.knightfrank.com>, Debashis <debashis.bhowmick@godrejproperties.com>, Abhikendra <abhikendra.saha@godrejproperties.com>

First of all Solve the below issues

1. Remove the advertisements from the walls of the entrance lift.
2. Solve the smelling of the water
3. Solve the logging of water in the roads.
4. Remove the AC Output of all the flats from the exterior walls..
5. Cracks on the exterior walls of the building

I have raised the above issues since 4 months and there is no resolutions yet.

I need to take the matter with the director and the head office of Godrej.

[Quoted text hidden]