

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 3         | Gr. Fl     |                           |                  |              |                  |
|           | 1st Fl     | B1                        | 664.35           | 74           |                  |
|           | 2nd Fl     | A1                        | 592.02           | 64           |                  |
|           |            | B1                        | 664.35           | 74           |                  |
|           | 3rd Fl     | C1                        | 865.43           | 112          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 4th Fl     | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           | 5th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           | 6th Fl     | C1                        | 865.43           | 131          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 7th Fl     | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           | 8th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 9th Fl     | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           | 10th Fl    | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           | 11th Fl    | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 12th Fl    | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | A1                        | 592.02           | 83           |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Singh*  
**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |  |
|-----------|------------|---------------------------|------------------|--------------|------------------|--|
|           |            |                           | sft.             | sft.         | sft.             |  |
|           | 13th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 14th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 15th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 16th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 17th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 18th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 19th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 20th Fl    | E1                        | 1344.64          | 163          |                  |  |
|           |            | A1                        | 592.02           | 83           |                  |  |
|           |            | B1                        | 664.35           | 97           |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | Gr. Fl     |                           |                  |              |                  |  |
|           |            | 1st Fl                    | B1               | 664.35       | 74               |  |
|           |            | 2nd Fl                    | A1               | 592.02       | 64               |  |
|           |            |                           | B1               | 664.35       | 74               |  |
|           |            |                           | C1               | 865.43       | 69               |  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*  
**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 4         | 3rd Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           | 4th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           | 5th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           | 6th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           | 7th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           | 8th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           |            | D1                        | 1118.59          | 124          |                  |
|           |            | D2                        | 1006.43          | 95           |                  |
|           | 9th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 88           |                  |
|           |            | D1                        | 1118.59          | 124          |                  |
| D2        |            | 1006.43                   | 95               |              |                  |
| 10th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 88               |              |                  |
|           | D1         | 1118.59                   | 124              |              |                  |
|           | D2         | 1006.43                   | 95               |              |                  |
| 11th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 88               |              |                  |
|           | D1         | 1118.59                   | 124              |              |                  |
|           | D2         | 1006.43                   | 95               |              |                  |
| 12th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 88               |              |                  |
|           | D1         | 1118.59                   | 124              |              |                  |
|           | D2         | 1006.43                   | 95               |              |                  |
| 13th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 88               |              |                  |
|           | D1         | 1118.59                   | 124              |              |                  |
|           | D2         | 1006.43                   | 95               |              |                  |
|           |            | A1                        | 592.02           | 83           |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*

**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction. | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|----------------------------|------------------|--------------|------------------|
|           |            |                            | sft.             | sft.         | sft.             |
|           | 14th Fl    | B1                         | 664.35           | 97           |                  |
|           |            | C1                         | 865.43           | 88           |                  |
|           |            | D1                         | 1118.59          | 124          |                  |
|           |            | D2                         | 1006.43          | 95           |                  |
|           | 15th Fl    | A1                         | 592.02           | 83           |                  |
|           |            | B1                         | 664.35           | 97           |                  |
|           |            | C1                         | 865.43           | 88           |                  |
|           |            | D1                         | 1118.59          | 124          |                  |
|           | 16th Fl    | D2                         | 1006.43          | 95           |                  |
|           |            | A1                         | 592.02           | 83           |                  |
|           |            | B1                         | 664.35           | 97           |                  |
|           |            | C1                         | 865.43           | 88           |                  |
|           | 17th Fl    | D1                         | 1118.59          | 124          |                  |
|           |            | D2                         | 1006.43          | 95           |                  |
|           |            | A1                         | 592.02           | 83           |                  |
|           |            | B1                         | 664.35           | 97           |                  |
|           | 18th Fl    | C1                         | 865.43           | 88           |                  |
|           |            | D1                         | 1118.59          | 124          |                  |
|           |            | D2                         | 1006.43          | 95           |                  |
|           |            | A1                         | 592.02           | 83           |                  |
| 19th Fl   | B1         | 664.35                     | 97               |              |                  |
|           | C1         | 865.43                     | 88               |              |                  |
|           | D1         | 1118.59                    | 124              |              |                  |
|           | D2         | 1006.43                    | 95               |              |                  |
| 20th Fl   | A1         | 592.02                     | 83               |              |                  |
|           | B1         | 664.35                     | 97               |              |                  |
|           | C1         | 865.43                     | 88               |              |                  |
|           | D1         | 1118.59                    | 124              |              |                  |
| Gr. Fl.   |            |                            |                  |              |                  |
| 1st Fl    | A2         | 635.51                     | 57               |              |                  |
|           | B2         | 723.45                     | 39               |              |                  |
|           | B3         | 686.31                     | 61               |              |                  |
| 2nd Fl    | A1         | 590.62                     | 58               |              |                  |
|           | A2         | 635.51                     | 57               |              |                  |
|           | B2         | 723.45                     | 39               |              |                  |
|           | B3         | 686.31                     | 61               |              |                  |
| 3rd Fl    | C3         | 844.33                     | 110              |              |                  |
|           | A1         | 590.62                     | 78               |              |                  |
|           | A2         | 635.51                     | 76               |              |                  |
|           |            | B2                         | 723.45           | 59           |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*

**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 5         |            | B3                        | 686.31           | 81           |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 4th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 5th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 6th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 7th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 8th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 9th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 10th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 11th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
| B2        |            | 723.45                    | 59               |              |                  |
| B3        |            | 686.31                    | 81               |              |                  |
| C2        |            | 917.74                    | 136              |              |                  |
| C3        |            | 844.33                    | 130              |              |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dugar*

**Director**

P S-Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | Gr. Fl.    |                           |                  |              |                  |
|           | 1st Fl     | A2                        | 635.51           | 57           |                  |
|           |            | B2                        | 723.45           | 39           |                  |
|           |            | B3                        | 686.31           | 61           |                  |
|           |            | B5                        | 657.25           | 65           |                  |
|           | 2nd Fl     | A1                        | 590.62           | 58           |                  |
|           |            | A2                        | 635.51           | 57           |                  |
|           |            | B2                        | 723.45           | 39           |                  |
|           |            | B3                        | 686.31           | 61           |                  |
|           |            | B4                        | 743.58           | 56           |                  |
|           | 3rd Fl     | B5                        | 657.25           | 65           |                  |
|           |            | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           | 4th Fl     | B4                        | 743.58           | 76           |                  |
|           |            | B5                        | 657.25           | 87           |                  |
|           |            | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           | 5th Fl     | B3                        | 686.31           | 81           |                  |
|           |            | B4                        | 743.58           | 76           |                  |
|           |            | B5                        | 657.25           | 87           |                  |
|           |            | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           | 6th Fl     | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | B4                        | 743.58           | 76           |                  |
|           |            | B5                        | 657.25           | 87           |                  |
|           |            | A1                        | 590.62           | 78           |                  |
|           | 7th Fl     | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | B4                        | 743.58           | 76           |                  |
|           |            | B5                        | 657.25           | 87           |                  |
|           | 8th Fl     | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dugga*  
**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 6         | 9th Fl     | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 10th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 11th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 12th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 13th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 14th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 15th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 16th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 17th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dugar*  
**Director**

**P S Group Realty Pvt. Ltd.**

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
|           | 12th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 13th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 14th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 15th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 16th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 17th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | 18th Fl    | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
| 19th Fl   | A1         | 590.62                    | 78               |              |                  |
|           | A2         | 635.51                    | 76               |              |                  |
|           | B2         | 723.45                    | 59               |              |                  |
|           | B3         | 686.31                    | 81               |              |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dugar*  
**Director**

**P S Group Realty Pvt. Ltd.**

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
|           | 20th Fl    | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           |            | A1                        | 590.62           | 78           |                  |
|           |            | A2                        | 635.51           | 76           |                  |
|           |            | B2                        | 723.45           | 59           |                  |
|           |            | B3                        | 686.31           | 81           |                  |
|           |            | C2                        | 917.74           | 136          |                  |
|           |            | C3                        | 844.33           | 130          |                  |
|           | GR FL.     |                           |                  |              |                  |
|           | 1st Fl     | A1                        | 592.02           | 64           |                  |
|           |            | B1                        | 664.35           | 74           |                  |
|           |            | C1                        | 865.43           | 112          |                  |
|           | 2nd Fl     | A1                        | 592.02           | 64           |                  |
|           |            | B1                        | 664.35           | 74           |                  |
|           |            | C1                        | 865.43           | 112          |                  |
|           |            | D1                        | 1118.59          | 103          |                  |
|           |            | E1                        | 1344.64          | 137          |                  |
|           | 3rd Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 4th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 5th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 6th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 7th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
| D1        |            | 1118.59                   | 130              |              |                  |
| E1        |            | 1344.64                   | 163              |              |                  |
| 8th Fl    | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |
|           | D1         | 1118.59                   | 130              |              |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dugar*  
Director

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
|           | 18th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 19th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 20th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | Gr. Fl.    |                           |                  |              |                  |
|           | 1st Fl.    |                           |                  |              |                  |
|           | 2nd Fl     | D1                        | 1118.59          | 103          |                  |
|           |            | E1                        | 1344.64          | 137          |                  |
|           | 3rd Fl     | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 4th Fl     | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 5th Fl     | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 6th Fl     | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 7th Fl     | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 8th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 9th Fl     | A1                        | 592.02           | 83           |                  |
| B1        |            | 664.35                    | 97               |              |                  |
| C1        |            | 865.43                    | 131              |              |                  |
| D1        |            | 1118.59                   | 130              |              |                  |
| E1        |            | 1344.64                   | 163              |              |                  |
| 10th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |
|           | D1         | 1118.59                   | 130              |              |                  |
|           | E1         | 1344.64                   | 163              |              |                  |
|           | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*

**Director**

**P S Group Realty Pvt. Ltd.**

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 7         | 11th Fl    | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 12th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 13th Fl    | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 14th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 15th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 16th Fl    | A1                        | 592.02           | 83           |                  |
| B1        |            | 664.35                    | 97               |              |                  |
| C1        |            | 865.43                    | 131              |              |                  |
| D1        |            | 1118.59                   | 130              |              |                  |
| E1        |            | 1344.64                   | 163              |              |                  |
| 17th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |
|           | D1         | 1118.59                   | 130              |              |                  |
|           | E1         | 1344.64                   | 163              |              |                  |
| 18th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |
|           | D1         | 1118.59                   | 130              |              |                  |
|           | E1         | 1344.64                   | 163              |              |                  |
| 19th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |
|           | D1         | 1118.59                   | 130              |              |                  |
|           | E1         | 1344.64                   | 163              |              |                  |
| 20th Fl   | A1         | 592.02                    | 83               |              |                  |
|           | B1         | 664.35                    | 97               |              |                  |
|           | C1         | 865.43                    | 131              |              |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dyer*

**Director**

**P S Group Realty Pvt. Ltd.**

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |  |
|-----------|------------|---------------------------|------------------|--------------|------------------|--|
|           |            |                           | sft.             | sft.         | sft.             |  |
| 8         |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           | 9th Fl     | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           | 10th Fl    | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           | 11th Fl    | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           | 12th Fl    | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           | 13th Fl    | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           | 14th Fl    | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           | 15th Fl    | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            |                           | B5               | 657.25       | 87               |  |
|           |            |                           | A1               | 590.62       | 78               |  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*  
**Director**

**P S Group Realty Pvt. Ltd.**

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |  |
|-----------|------------|---------------------------|------------------|--------------|------------------|--|
|           |            |                           | sft.             | sft.         | sft.             |  |
|           | 16th Fl    | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           | 17th Fl    | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           |            | B4                        | 743.58           | 76           |                  |  |
|           | 18th Fl    | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
|           |            | B3                        | 686.31           | 81           |                  |  |
|           | 19th Fl    | B4                        | 743.58           | 76           |                  |  |
|           |            | B5                        | 657.25           | 87           |                  |  |
|           |            | A1                        | 590.62           | 78           |                  |  |
|           |            | A2                        | 635.51           | 76           |                  |  |
|           |            | B2                        | 723.45           | 59           |                  |  |
| 20th Fl   | B3         | 686.31                    | 81               |              |                  |  |
|           | B4         | 743.58                    | 76               |              |                  |  |
|           | B5         | 657.25                    | 87               |              |                  |  |
|           | A1         | 590.62                    | 78               |              |                  |  |
|           | A2         | 635.51                    | 76               |              |                  |  |
|           | Gr. Fl.    |                           |                  |              |                  |  |
|           | 1st Fl     | E1                        | 1344.64          | 137          |                  |  |
|           |            | C1                        | 865.43           | 112          |                  |  |
|           | 2nd Fl     | D1                        | 1118.59          | 103          |                  |  |
|           |            | E1                        | 1344.64          | 137          |                  |  |
|           | 3rd Fl     | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           | 4th Fl     | E1                        | 1344.64          | 163          |                  |  |
|           |            | C1                        | 865.43           | 131          |                  |  |
|           | 5th Fl     | D1                        | 1118.59          | 130          |                  |  |
|           |            | E1                        | 1344.64          | 163          |                  |  |
|           | 6th Fl     | C1                        | 865.43           | 131          |                  |  |
|           |            | D1                        | 1118.59          | 130          |                  |  |
|           |            |                           | E1               | 1344.64      | 163              |  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*  
**Director**

P S Group Realty Pvt. Ltd.

| Tower No. | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area | Terrace (if any) |
|-----------|------------|---------------------------|------------------|--------------|------------------|
|           |            |                           | sft.             | sft.         | sft.             |
| 9         | 7th Fl     | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 8th Fl     | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 9th Fl     | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 10th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           | 11th Fl    | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           | 12th Fl    | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           | 13th Fl    | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           |            | A1                        | 592.02           | 83           |                  |
|           | 14th Fl    | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 15th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |
|           |            | D1                        | 1118.59          | 130          |                  |
|           |            | E1                        | 1344.64          | 163          |                  |
|           | 16th Fl    | A1                        | 592.02           | 83           |                  |
|           |            | B1                        | 664.35           | 97           |                  |
|           |            | C1                        | 865.43           | 131          |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dya*  
**Director**

P S Group Realty Pvt. Ltd.

| Tower No.    | Floor Mkd. | Flat Mkd. As Per sanction | Flat Carpet Area | Balcony Area    | Terrace (if any) |
|--------------|------------|---------------------------|------------------|-----------------|------------------|
|              |            |                           | sft.             | sft.            | sft.             |
|              |            | D1                        | 1118.59          | 130             |                  |
|              |            | E1                        | 1344.64          | 163             |                  |
|              | 17th Fl    | A1                        | 592.02           | 83              |                  |
|              |            | B1                        | 664.35           | 97              |                  |
|              |            | C1                        | 865.43           | 131             |                  |
|              |            | D1                        | 1118.59          | 130             |                  |
|              |            | E1                        | 1344.64          | 163             |                  |
|              | 18th Fl    | A1                        | 592.02           | 83              |                  |
|              |            | B1                        | 664.35           | 97              |                  |
|              |            | C1                        | 865.43           | 131             |                  |
|              |            | D1                        | 1118.59          | 130             |                  |
|              |            | E1                        | 1344.64          | 163             |                  |
|              | 19th Fl    | A1                        | 592.02           | 83              |                  |
|              |            | B1                        | 664.35           | 97              |                  |
|              |            | C1                        | 865.43           | 131             |                  |
|              |            | D1                        | 1118.59          | 130             |                  |
|              |            | E1                        | 1344.64          | 163             |                  |
|              | 20th Fl    | A1                        | 592.02           | 83              |                  |
|              |            | B1                        | 664.35           | 97              |                  |
|              |            | C1                        | 865.43           | 131             |                  |
| D1           |            | 1118.59                   | 130              |                 |                  |
| E1           |            | 1344.64                   | 163              |                 |                  |
| <b>TOTAL</b> |            |                           | <b>545648.9</b>  | <b>68017.84</b> |                  |

**PS GROUP REALTY PVT. LTD.**

*Ravi Kumar Dey*  
**Director**

**P S Group Realty Pvt. Ltd.**