

BLOCK-WISE DETAILS						
WING	NO.OF FLOOR	1BHK	2BHK	3BHK	4BHK	TOTAL
TULIP APARTMENT	G+3	0	6	15	0	21
TOTAL		0	6	15	0	21

WING	FLOOR	UNIT NO.	BHK	FLAT NO.	CARPET AREA (sq.m.)	BALCONY AREA (EXCLUSIVE) (sq.m.)
TULIP APARTMENT	1ST	A	3	1A	79.384	6.24
TULIP APARTMENT	1ST	B	3	1B	79.633	6.248
TULIP APARTMENT	1ST	C	2	1C	54.335	2.723
TULIP APARTMENT	1ST	D	2	1D	77.479	5.782
TULIP APARTMENT	1ST	E	3	1E	57.455	2.565
TULIP APARTMENT	1ST	F	3	1F	79.401	6.03
TULIP APARTMENT	1ST	G	3	1G	79.602	6.229
TULIP APARTMENT	2ND	A	3	2A	79.384	6.24
TULIP APARTMENT	2ND	B	3	2B	79.633	6.248
TULIP APARTMENT	2ND	C	2	2C	54.335	2.723
TULIP APARTMENT	2ND	D	3	2D	77.479	5.782
TULIP APARTMENT	2ND	E	2	2E	57.455	2.565
TULIP APARTMENT	2ND	F	3	2F	79.401	6.03
TULIP APARTMENT	2ND	G	3	2G	79.602	6.229

Vanshidhar Vinimay (P) Ltd.
Ranjana Tyagi
 Director

VANSHIDHAR VINIMAY PRIVATE LIMITED



TULIP APARTMENT	3RD	A	3	3A	79.384	6.24
TULIP APARTMENT	3RD	B	3	3B	79.633	6.248
TULIP APARTMENT	3RD	C	2	3C	54.335	2.723
TULIP APARTMENT	3RD	D	3	3D	77.479	5.782
TULIP APARTMENT	3RD	E	2	3E	57.455	2.565
TULIP APARTMENT	3RD	F	3	3F	89.753	17.129
TULIP APARTMENT	3RD	G	3	3G	60.883	2.756
TOTAL AREA					1513.5	115.077

Vanshidhar Vinimay (F) Ltd.

Ranjana Agarwal
Director