

# SAMBIT CHATTERJEE

ARCHITECT

Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258.

(M) 8910182428.

=====

**SUB:** Architect Certificate till 30.09.2024 for a G+3 Storied residential Building Namely **M.Q RESIDENCY** situated at Mouza - KAIKHALI, JL No. 05, R.S. No. 150, R.S./L.R. Dag No. 357, L.R. Khatian No. 2202, 2203, 2204, Ward No. 06, P.S- Airport, Under Bidhannagar Municipal Corporation.

**WBRERA No. WBRERA/P/NOR/2023/000717**

## ARCHITECTCERTIFICATE

SLNO.	DESCRIPTION	DETAILS
1.	BUILDING / WING NUMBER (to be Prepared separately for each Building / Wing of the Project)	1
2.	Excavation* (Percentage of work done)	100%
3.	Basement(s) and Plinth Percentage of work done)	Basement – Not Applicable Plinth – 100 %
4.	Number of Basement(s) and Plinth*	Basement – 0 Plinth – 1
5.	Podiums Percentage of work done*	Not Applicable
6.	Number of Podiums*	Not Applicable
7.	Stilt Floor Percentage of work done*	Not Applicable
8.	Slabs of Super Structure Percentage of work done*	100 %
9.	Number of Slabs of Super Structure	4 Nos.
10.	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises Percentage of work done*	80 %
11.	Sanitary Fittings within the Flat/Premises Percentage of work done*	50 %
12.	Electrical Fittings within the Flat/Premises Percentage of work done*	50%
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Over head and Underground Water Tanks Percentage of work done*	100 %
14.	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the Building/Wing Percentage of work done*	80%

# SAMBIT CHATTERJEE

ARCHITECT

Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258.

(M) 8910182428.

15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be Required to Obtain Occupation /Completion Certificate Percentage of work done*	70%
16.	Architect Certificate regarding progress Of work.	

## COMMON AREAS AND FACILITIES, AMENITIES DETAILS

SLNO.	DESCRIPTION	DETAILS
1.	Internal Roads & Footh paths Percentage of work done*	NA
2.	Water Supply Percentage of work done*	90%
3.	Sewerage (chamber, lines, Septic Tank , STP) Percentage of work done*	90%
4.	Storm Water Drains Percentage of work done*	NA
5.	Landscaping & Tree Planting Percentage of work done*	NA
6.	Street Lighting Percentage of work done*	NA
7.	Community Buildings Percentage of work done*	NA
8.	Treatment and disposal of sewage and sullage water Percentage of work done*	90%
9.	Solid Waste management & Disposal Percentage of work done*	90%
10.	Water conservation, Rain water harvesting Percentage of work done*	NA
11.	Energy management Percentage of work done*	NA
12.	Fire protection and fire safety requirements Percentage of work done*	NA
13.	Electrical meter room, sub-station, receiving station Percentage of work done*	70%

*Sambit Chatterjee*

**SAMBIT CHATTERJEE**  
**REGISTERED ARCHITECT**  
CA / 2003 / 32116

Page 2 of 2

