## SAMBIT CHATTERJEE

**ARCHITECT** 

Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258.

(M) 8910182428.

\_\_\_\_\_\_

SUB: Architect Certificate till 30/09/2024 for a G+4 Storied residential Building Namely BENGAL AASHIYANA situated at Mouza- SALUA, JL No. 03, R.S. No. 109, Touzi No. 2998, R.S./L.R. Dag No. 286, 287, L.R. Khatian No. 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, Ward No. 04, P.S- Airport, Under Bidhannagara Municipal Corporation.

ARCHITECT CERTIFICATE

SLNO.	DESCRIPTION	DETAILS
1.	BUILDING / WING NUMBER (to be Prepared separately for each Building / Wing of the Project)	1
2.	Excavation* (Percentage of work done)	100%
3.	Basement(s) and Plinth Percentage of work done)	Basement – Not Applicable Plinth – 100 %
4.	Number of Basement(s) and Plinth*	Basement – 0 Plinth – 1
5.	Podiums Percentage of work done*	Not Applicable
6.	Number of Podiums*	Not Applicable
7.	Stilt Floor Percentage of work done*	Not Applicable
8.	Slabs of Super Structure Percentage of work done*	80 %
9.	Number of Slabs of Super Structure	5 Nos.
10.	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises  Percentage of work done*	
11.	Sanitary Fittings within the Flat/Premises Percentage of work done*	0 %
12.	Flat/Premises Percentage of work done*	0%
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Over head and Underground Water Tanks Percentage of work done*	60 %
14.	The external plumbing and external plaster, elevation, completion of terraces with water proofing of the Building/Wing Percentage of work done*	

Scanned with OKEN Scanner

## SAMBIT CHATTERJEE

ARCHITECT Address: 87, R.K Street, Uttarpara, Hooghly, PIN 712258. (M) 8910182428.

======	:======================================
15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of Areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be Required to Obtain Occupation /Completion Certificate Percentage of work done*  Architect Certificate regarding progress
16.	
	Of work.

	OT WORK	TIESDETAILS
	COMMONAREASANDFACILITIES, AMENI	DETAILS
SLNO.	DESCRIPTION	NA
1.	Internal Roads & Footh paths	
	b-weentage of work done"	0%
2.	Water Supply Percentage of work done*	
۷.	Gartie Tank STP)	0%
3.	Sewerage (chamber, lines, Septic Tank, STP)	
	Percentage of work done	0%
<del></del>	Storm Water Drains Percentage of work done*	0%
4.	Storm water = -	0%
	Landscaping & Tree Planting Percentage of work	.078
5.		NA
	t i abting Percentage of Work done	
6.	Community Buildings Percentage of work done*	NA
7.		0007
	Treatment and disposal of sewage and sullage	0%
8.	water Percentage of work done*	
	Solid Waste management & Disposal	0%
9.	- Truckly done	
	Percentage of work done*  Water conservation, Rain water harvesting	0%
10.	Water conservation, Ram water	
	Percentage of work done*	NA
11.	Energy management	
	- 4 of WORK HOUE	0%
12.	Fire protection and fire safety requirements	
	Dargentage of Work done	0%
12	Electrical meter room, sub-station, receiving	070
13.	station	
	Percentage of work done*	
	retooniage of	

Page 2 of 2

SAMBIT CHATTERJEE REGISTERED ARCHITECT CA / 2003 / 32116