ARCHITECTCERTIFICATE

SLNO.	DESCRIPTION	DETAILS
1.	BUILDING/WINGNUMBER(to be	No of Building: One
	Prepared separately for each Building	
	/Wing of the Project)	
2.	Excavation*	100% Completed
	(Percentage of work done)	
3.	Basement(s) and Plinth	Plinth work 80% Completed
	(Percentage of work done)*	
4.	Number of Basement(s) and Plinth*	NA NA
5.	Podiums	NA
J,	Percentage of work done*	
6.	Number of Podiums*	NA
7.	Stilt Floor	NA
/.	Percentage of work done*	147 x
8.	Slabs of Super Structure	Work in Progress
Ο.	Percentage of work done*	WOIK III I TOGICSS
	rercentage of work done	
9.	Number of Slabs of Super Structure	6 Nos
10.	Internal walls, Internal Plaster, Floorings	0%
	within Flats/Premises, Doors and Windows	
	to each of the Flat/Premises	·
	Percentage of work done*	
11.	Sanitary Fittings within the	0%
	Flat/Premises	Section 2
	Percentage of work done*	
12.	Electrical Fittings within the Flat/Premises	0%
	Percentage of work done*	. *
13.	Staircases, Lifts Wells and Lobbies at each	0%
10.	Floor level connecting Staircases and	
	Lifts, Overhead and Underground Water	
	Tanks	
	Percentage of work done*	\$
14.	The external plumbing and external plaster,	0%
	elevation, completion of terraces with	
	waterproofing of the Building/Wing	
	Percentage of work done*	
15.	Installation of lifts, water pumps, Fire	0%
	Fighting Fittings and Equipment as per CFO	
	NOC, Electrical fittings to Common Areas,	
	electro, mechanical equipment, Compliance	
	to conditions of environment	
	/CRZ NOC, Finishing to entrance	
	lobby/s, plinth protection, paving of	

	Are as appurtenant to Building/Wing,	
	Compound Wall and all other	
	requirements as may be	
	Required to Obtain Occupation	
	/Completion Certificate	
	Percentage of work done*	
16.	Architect Certificate regarding progress	
	Of work.	

COMMONAREASANDFACILITIES, AMENITIES DETAILS

SLNO.	DESCRIPTION	DETAILS
1.	Internal Roads & Footh paths	0%
 -	Percentage of work done*	
2.	Water Supply	0%
	Percentage of work done*	
3.	Sewerage(chamber, lines, Septic Tank,	0%
	STP) Percentage of work done*	
4.	Storm Water Drains	0%
т.	Percentage of work done*	
5.	Landscaping & Tree Planting	0%
0.	Percentage of work done*	
6.	Street Lighting	0%
	Percentage of work done*	
7.	Community Buildings	0%
	Percentage of work done*	
8.	Treatment and disposal of sewage and	0%
	sullage water	
	Percentage of work done*	A section of
9.	Solid Waste management & Disposal	0%
	Percentage of work done*	
10.	Water conservation, Rain water	0%
	harvesting	•
	Percentage of work done*	
11.	Energy management	0%
	Percentage of work done*	
12.	* Fire protection and fire safety	0%
	requirements	· · · · · · · · · · · · · · · · · · ·
	Percentage of work done*	
13.	Electrical meter room, sub-station,	Stageth 0%
	receiving station	
	Percentage of work done* KAUSHIK	ABHILASH DASGUPTA

B.ARCH REG. NO. CA/2003/30828 COUNCIL OF ARCHITECTURE ARCH/HIDCO/09/00038