


ARCHITECT CERTIFICATE

SLNO.	DESCRIPTION	DETAILS
1.	BUILDING/WING NUMBER (to be Prepared separately for each Building /Wing of the Project)	No of Building : One
2.	Excavation* (Percentage of work done)	100% Completed
3.	Basement(s) and Plinth (Percentage of work done)*	Plinth work 90% Completed
4.	Number of Basement(s) and Plinth*	NA
5.	Podiums Percentage of work done*	NA
6.	Number of Podiums*	NA
7.	Stilt Floor Percentage of work done*	NA
8.	Slabs of Super Structure Percentage of work done*	Work in Progress
9.	Number of Slabs of Super Structure	6 Nos
10.	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises Percentage of work done*	0%
11.	Sanitary Fittings within the Flat/Premises Percentage of work done*	0%
12.	Electrical Fittings within the Flat/Premises Percentage of work done*	0%
13.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks Percentage of work done*	0%
14.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing Percentage of work done*	0%
15.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of	0%

	Are as appurtenant to Building/Wing, Compound Wall and all other requirements as may be Required to Obtain Occupation /Completion Certificate Percentage of work done*	
16.	Architect Certificate regarding progress Of work.	

COMMON AREAS AND FACILITIES, AMENITIES DETAILS

SLNO.	DESCRIPTION	DETAILS
1.	Internal Roads & Foot paths Percentage of work done*	0%
2.	Water Supply Percentage of work done*	0%
3.	Sewerage(chamber, lines, Septic Tank , STP) Percentage of work done*	0%
4.	Storm Water Drains Percentage of work done*	0%
5.	Landscaping & Tree Planting Percentage of work done*	0%
6.	Street Lighting Percentage of work done*	0%
7.	Community Buildings Percentage of work done*	0%
8.	Treatment and disposal of sewage and sullage water Percentage of work done*	0%
9.	Solid Waste management & Disposal Percentage of work done*	0%
10.	Water conservation, Rain water harvesting Percentage of work done*	0%
11.	Energy management Percentage of work done*	0%
12.	Fire protection and fire safety requirements Percentage of work done*	0%
13.	Electrical meter room, sub-station, receiving station Percentage of work done*	0%


KAUSHIK ABHILASH DASGUPTA
B.Arch
 REG. NO. CA/2003/30828
 COUNCIL OF ARCHITECTURE
 ARCH/HIDCO/09/00038