



### Online Plinth Level Completion Declaration

#### Completion of Work Up To Plinth Level

Search Criteria (Sanction No)

Sanction No: 2022120189

Search

#### Sanction details

##### Sanction Details

Plan Case No: 2022120170

Sanction No: 2022120189

Sanction Date: 07/07/2022

Premises No: 34

Street Name: ROYPUR

Ward: 101

Owner Name: SRI BIPLAB GANGULY, SMT REKHA MOITRA, SMT MINATI CHAKRABORTY, SMT PAPIYA CHAKRABORTY,

Borough No: 12

#### Applicant Name and Address

Applicant Name: DOLAN DAS & TWO OTHER CA OF B GANGULY THREE OTHERS

Applicant Address 1: 57C RAIPUR

Applicant Address 2: KOLKATA

Applicant Pin: 700084

#### LBS/Architect,ESE,ESR,GT Details

LBS/Architect No: LBS/M/781

LBS/Architect Name: SAKTIBRATA BHATTACHERJEE

ESE Code: ESE/II/60

Change ESE

ESE Name: KALLOL KUMAR GHOSHAL

ESR Code:

Change ESR

ESR Name:

GT Code: G.T/II/14

Change GT

GT Name: KALLOL KUMAR GHOSHAL

#### As per sanction

Ground Cover area: 148.907

Total Floor Area : 595.628

No of lift: 1

No of Escalator: 0

#### If any changes in Plinth level

Building footprint changes?:  Y  N

#### Necessary Document Upload for Plinth Submission

Environmental Clearance

Consent To Establish

Undertaking

Soil Test Report

Soil Test Report doc:  S\_T.pdf

Structural Design

Structural Design Calculations

I Agree:  I hereby certify that the construction work completed up to plinth level is in compliance of the KMC Building Rules 2009 with subsequent amendments. I further certify that all the works done is structurally safe & stable in all respect .





Home

Logout

### Online Plinth Level Completion Declaration

#### Completion of Work Up To Plinth Level

Search Criteria (Sanction No)

Sanction No: 2022120189

Search



#### Sanction details

##### Sanction Details

**Please Note**  
Plinth Level Declaration of Sanction No: 2022120189 has been submitted. Plinth No Is:2022120159

OK

AB GANGULY, SMT REKHA  
MINATI CHAKRASORTY,  
CHAKRABORTY,

Street Name: ROYPUK  
Ward: 101  
Borough No: 12

#### Applicant Name and Address

Applicant Name: DOLAN DAS & TWO OTHER DA OF B GANGULY THREE OTHERS  
Applicant Address 1: 57C RAIPUR  
Applicant Address 2: KOLKATA  
Applicant Pin: 700084

#### LBS/Architect,ESE,ESR,GT Details

LBS/Architect No: LBSA/781 LBS/Architect Name: SAKTIBRATA BHATTACHERJEE  
ESE Code: ESE/1/60 Change ESE ESE Name: KALLOL KUMAR GHOSHAL  
ESR Code: Change ESR ESR Name:  
GT Code: G.T/1/14 Change GT GT Name: KALLOL KUMAR GHOSHAL

#### As per sanction

Ground Cover area: 146.907 Total Floor Area : 595.626  
No of lift: 1 No of Escalator: 0  
Building footprint changes?:  Y  N

#### Necessary Document Upload for Plinth Submission

Environmental Clearance

Consent To Establish

Undertaking

Soil Test Report

Soil Test Report doc:: Choose File S\_T.pdf

Structural Design

Structural Design Calculations

I Agree:  I hereby certify that the construction work completed up to plinth level is in compliance of the KMC Building Rules 2009 with subsequent amendments. I further certify that all the works done is structurally safe & stable in all respect .

Submit