

**1. Status and construction of building with photograph-** mentioning blocks, each floor starting from floor-1 and construction status.

**SUB-STRUCTURE:** RCC work 100% complete.

**SUPER-STRUCTURE:**

**RCC WORK:** Upto Roof slab 100% complete  
Above Roof slab work in progress.

**BRICKWORK:** 2<sup>nd</sup> to 4<sup>th</sup> floor 100% complete  
Ground floor, 1<sup>st</sup> floor, 5<sup>th</sup> to 7<sup>th</sup> floor work in progress

**PLASTERWORK:** 2<sup>nd</sup> floor work in progress

**FLOORING WORK:** 2<sup>nd</sup> floor work in progress

**2. Construction status of internal infrastructure-photograph with description (e.g stp, ugr)**

**UGR:** RCC work 100% complete

**SEPTIC TANK:** No progress as of now

**DRIVEWAY:** No progress as of now

**EXTERNAL DRAINAGE:** No progress as of now

**3. Construction Status of common area-photograph with description (e.g-lift well, fire refuge, stair case, lobbies etc.)**

**COMMON AREA:**

**BRICKWORK:** 1<sup>st</sup> to 5<sup>th</sup> floor 100% complete  
Ground floor, 5<sup>th</sup> to 6<sup>th</sup> floor work in progress