

1. Status and construction of building with photograph- mentioning blocks, each floor starting from floor-1 and construction status.

- Sub Structure : 100% work completed.
- Super Structure : 100% work completed.
- Brick work : 100 % work completed.
- Plaster : Ground floor to 9<sup>th</sup> floor completed & 10<sup>th</sup> floor work in progress
- Finishing work : Work in progress


2. Construction status of internal infrastructure-photograph with description(e.g stp, ugr)

- UGR : RCC work & finishing work completed.
- Septic tank : Work in progress
- Driveway : Work in progress
- External Drainage - Work in progress

3. Construction Status of common area-photograph with description(e.g- lift well, fire refuge, stair case)

- Plaster : Ground floor to 9<sup>th</sup> floor completed & 10<sup>th</sup> floor in progress
- Stair flooring : 1<sup>st</sup> to 6<sup>th</sup> complete, 7<sup>th</sup> to roof in progress
- Finishing work: Finishing work in progress

PS GROUP REALTY PVT. LTD.



Director / Authorised Signatory