Department	Information Required	Status	Remarks / Any Issues
	Status of Project:		-
Projects	Status of Construction of Each Building with Photographs	All Sub Structure Work Completed Superstructure And Finishing Work In Progress	
	Building Name -	BLOCK-MLCP,PHASE VI	
	Main Entrance	PRIMARC	
	Building Elevation & Superstructure		Roof Slab Complete,1Above Roof WIP