

Vaanya

Refer block wise photographs for progress of work. Also find below the status of work in **Red** till 15.02.24.

1. **Status and construction of each building with photograph-mentioning blocks, each floor starting from floor-1 and construction status.**

- **Tower 1 : Piling work 100% completed. Foundation work in Progress.**
- **Tower 2 : Piling work 100% completed. Raft Foundation 100% completed. Column and wall above foundation in progress.**
- **Tower 3 : Piling work 100% completed. Foundation work in Progress.**
- **Tower 4 : Piling work 100% completed. Foundation work in Progress.**
- **Podium : Piling work 100% completed. Foundation work in Progress.**

2. **Construction status of internal infrastructure-photograph with description(e.g stp,ugr)**

- **UGR : Piling work 100% completed. Foundation work in progress.**
- **STP : Piling work 100% completed. Foundation work to be started soon.**

3. **Construction Status of common area-photograph with description(e.g-lift well,fire refuge,stair case)**

- **Piling work 100% completed for all tower. Foundation completed in Tower 2. Wall activity above foundation in progress.**

PS VINAYAK HOMES LL.


Partner / Authorised Signatory