

1. Status and construction of building with photograph- mentioning blocks, each floor starting from floor-1 and construction status.

- Sub Structure : 100% work completed.
- Super Structure
- 1st floor : 100 % RCC work completed.
2nd floor : 100 % RCC work completed.
- 3rd floor : 100 % RCC work completed.
- 4th floor : 80 % RCC work completed.

Common area Brickwork - 1st floor - 60% done, 2nd floor- 40% done.


2. Construction status of internal infrastructure-photograph with description(e.g stp, ugr)

- UGR : RCC work completed.
- Driveway : No progress as of now
- External Drainage - No progress as of now

3. Construction Status of common area-photograph with description(e.g-lift well, fire refuge, stair case)

- No progress as of now, brick work yet to be started.

SKIES ENCLAVE LLP



Director/Authorised Signatory