

1. Status and construction of building with photograph- mentioning blocks, each floor starting from floor-1 and construction status.

- Sub Structure : 100% work completed.
- Super Structure
 - Roof floor: 100 % RCC work completed.
 - Above roof floor : Work in progress.
- Brickwork: 5th floor - 100% done, 6th floor - Work in progress.
- Plasterwork: 5th floor - 100% done, 6th floor - Work in progress.
- Finishes work: Work in Progress

2. Construction status of internal infrastructure-photograph with description(e.g stp,ugr)

- UGR : RCC & Tiling work complete.
- Driveway : Work in Progress
- External Drainage - 100% done

3. Construction Status of common area-photograph with description(e.g-lift well, fire refuge, stair case)

- Brickwork: 5th floor - 100% done, 6th floor - Work in progress.
- Plasterwork: 5th floor - 100% done, 6th floor - Work in progress.
- Finishes work: Work in Progress
- Stair Tiling work -4th floor - 100%, 5th Floor - Work in progress

SKIES ENCLAVE LLP

Director/Authorised Signatory