

<b>TOWER 3 WORK PROGRESS</b>		
<b>TASK</b>	<b>STATUS</b>	<b>COMPLETION%</b>
EXCAVATION	Done	100%
FOOTING	Done	100%
COLUMN UPTO PLINTH	Done	100%
BACKFILLING IN FOOTING	Done	100%
<b>PLINTH BEAM</b>	Done	100%
EARTH FILLING IN PLINTH	Done	100%
ANTI TERMITE TREATMENT	Done	100%
<b>GF SLAB CASTING</b>	In progress	85%
COLUMN GF TO 1ST FLOOR	Done	100%
<b>1F SLAB CASTING</b>	Done	100%
GF BRICK WORK	Done	100%
GF INTERNAL PLASTER	In progress	90%
COLUMN 1ST FLOOR TO 2ND FLOOR	Done	100%
<b>2F SLAB CASTING</b>	Done	100%
1F BRICK WORK	Done	100%
1F INTERNAL PLASTER	Done	100%
COLUMN 2ND FLOOR TO 3RD FLOOR	Done	100%
<b>3F SLAB CASTING</b>	Done	100%
2F BRICK WORK	Done	100%
2F INTERNAL PLASTER	Done	100%
COLUMN 3RD FLOOR TO 4TH FLOOR	Done	100%
<b>4F SLAB CASTING</b>	Done	100%
3F BRICK WORK	Done	100%
3F INTERNAL PLASTER	Done	100%
COLUMN 4TH FLOOR TO 5TH FLOOR	Done	100%
<b>5F SLAB CASTING</b>	Done	100%
4F BRICK WORK	Done	100%
4F INTERNAL PLASTER	Done	100%
COLUMN 5TH FLOOR TO ROOF	Done	100%
<b>ROOF SLAB CASTING</b>	Done	100%
5F BRICK WORK	Done	100%
5F INTERNAL PLASTER	Done	100%
COLUMN ROOF TO LIFT MOTOR ROOM LVL.	Done	100%
<b>LIFT MOTOR ROOM SLAB CASTING</b>	Done	100%
ROOF BRICK WORK	Done	100%
ROOF INTERNAL PLASTER	Done	100%
STAIRCASE BRICKWORK	Done	100%
STAIRCASE PLASTER	Done	100%

EXTERNAL PLASTER	Done	100%
------------------	------	------