

WB-HIRA : "Progress Report" as on 31.12.18

Development Work Plan : Merlin Gangotri (As on 31.12.2018)			
Sl. No.	Common areas And Facilities, Amenities	Percent Complete (Approx)	Work Description
1	Internal Roads	0%	
2	Potable and Treated Water Supply	0%	
3	Sewerage (Chamber, Lines, STP) :	0%	
4	Storm Water (Drains, chambers & Lines)	0%	
5	Landscaping , Tree Planting & Hardscape	0%	
6	General Illumination and common Area Lighting	0%	
9	Swimming Pool	0%	
10	Common Amenities : Community hall, Gym, Indoor games, Yoga room, Toddlers room	0%	
11	Fire Protection And Fire Safety Requirements	0%	
12	Electrical Meter & Transformer space	0%	
13	Open areas for recreational Space including Rooftop amenities	0%	
Sl. No	Tasks / Activity	Percentage of Work	
1	Excavation	75%	
2	Basement(s)	50%	
3	Stilt Floor	15%	
4	Slabs of Super Structure	15%	
5	Internal Masonry walls & Plaster	0%	
6	Floorings within Flats/Complex	0%	
7	Doors and Windows in each of the Flat/Premises	0%	
8	Sanitary Fittings within the Flat/Premises,Electrical Fittings within the Flat/Premises	0%	
9	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0%	
10	The external plumbing and external plaster, elevation	0%	
11	Completion of terraces with waterproofing of the Building/Complex	0%	
12	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per WBFES NOC, Electrical fittings to Common Areas, electro-mechanical equipment, Finishing to entrance lobby/s, paving of areas appurtenant to Building/Complex, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	