

Development Work Status of Merlin Urvan

Sr.No.	Common areas And Facilities, Amenities	Percent Complete (Approx)
1	Internal Roads	0
2	Potable and Treated Water Supply	0
3	Sewerage (Chamber, Lines, STP) :	0
4	Storm Water (Drains, chambers & Lines)	0
5	Landscaping , Tree Planting & Hardscape	0
6	General Illumination and common Area Lighting	0
9	Swimming Pool	0
10	Common Amenities : Community hall, Gymnasium, Indoor games room, SPA, Resident's Club	0
11	Fire Protection And Fire Safety Requirements	0
12	Electrical Meter & Transformer space	0
13	Open areas for recreational Space	0

Sr.No.	Tasks / Activity	Percentage of Work
1	Excavation	0
2	Foundation & Basement	0
3	Stilt Floor	0
4	Slabs of Super Structure	0
5	Internal Masanory walls & Plaster	0
6	Tiling work within Flats	0
7	Tiling Work in common areas	
8	Doors and Windows	0
9	Sanitary Fittings within the Flat/Premises	0
10	Electrical Fittings within the Flat/Premises	0
11	Staircases, Lifts Wells and,common Lobbies, Overhead and Underground Water Tanks.	0
12	The external plumbing and house drainage works	0
13	External Elevation work	
14	Completion of rooftop/terraces with waterproofing of the Building/Complex whereever required	0
15	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per WBFES NOC, Electrical fittings in Common Areas, electro-mechanical equipments, Finishing of entrance lobby/s, paving of common areas appurtenant to Building/Complex, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0 MERI IN P

MERLIN PROJECTS LTD

Authorised Signator(3s/Directo