

Photographs as proof



Flash Doors without lamination



Faulty Drainage System leads to water log



Poor Condition of Internal drive way



Poor Condition of Outer grass drive way



Water leakage from roof of covered parking during rainfall