

Santimoy Kundu

B.Tech (Civil), LBS Class – 1, No. 1556
Geo-Tech Engg. No. – GT/II/13
Kolkata Municipal Corporation

RB-13, Raghunathpur,
Kolkata – 700059, (M) 9830024728

To whom it may concern

This is to certify that, job progress report of Nupur Ropy & Other Mouza – mahisgoat, R.S. Dag No. 137, in ward No. 27, under Bidhannagar Municipal Corporation is as follows :

1. Earth in excavation (50% of total construction area)
2. Sand filling
3. B.F.S.
4. P.C.C. &
5. Column concreting work with re-enforcement cutting, bending – binding upto pedestal level i.e. below the tie-beam level for column MKD – C24, C25, C26, C27, C28, C29, C30, C31, C32, C33, C34, C35, C36, C37, C38, C39, C40, C41, C42, C43, C44, C44, C45, C46 and remaining portions earth curring work is going on.


SANTIMOY KUNDU
LBS Class-1, KMC, No.-1556
Enlisted Civil Engg. NKDA,
No.-CVER/NKDA/10/00135 01/11/19