



**STATEMENT OF PROGRESS OF THE PROJECT**

**Project Name: SHAONLI**  
Kuthirmath Road (West), Chandernagore, Hooghly

**Completed Work: 65 %**

1. R.C.C. Framework Complete.
2. All inside and outside wall Brickwork and Plastering complete.
3. All inside wall putty complete
4. All outside plumbing work complete
5. Marble Flooring work at Toilet and Kitchen complete
6. Outside Primer complete
7. All door frame installed and window frame and shutter complete
8. All electric conceal and plumbing conceal work complete

**Work in Progress: 15 %**

1. Bed room and Living & Dining flooring and Wall tiles at Kitchen and Toilet work in progress
2. All inside wall putty work in progress
3. Electrical wiring in progress
4. Lift installation in progress

**Work Pending: 20 %**

1. All grill work pending
2. All Door window shutter pending
3. All Sanitary fittings pending
4. Electric transformer pending
5. Outside painting pending
6. Installation of door shutter is pending

Certified by:

**ANJAN DAS**  
C.O.A. Regd. Architect  
CA / 2003 / 31495

Signature with Seal

**( ANJAN DAS )**  
Project Architect

Date : 16.12.2019