


Aluminium window frame fixing



Electrical conduit pipe fixing 13th floor



Brick works at 17th floor



Internal plaster work 8th floor



Internal putty work at 4th floor



Door frame fixing at 4th floor



Internal fire line fixing 7th floor



Internal flooring work at 2nd floor

