

## Status of Construction of Common Infrastructure with Photographs :-

### A. INTERNAL BOUNDARY WALL 60% COMPLETED:



**B. MAINGATE PLAZA COMPLETED:**

